


寸法図



1AAMS00070A01

単位 : mm

	(A)	(B)	(C)	(D)	(E)	(F)	(G)	(H)	(I)	(J)	(K)	(L)	(M)
KX057-6S2	750	550	1960	5820	4160	3890	3070	1270	1820	6260	440	410	2550

	(N)	(O)	(P)	(Q)	(R)	(S)	(T)	(U)
KX057-6S2	1960	6130	5520	1825	2450	1990	2500	4100